

Promat

Promat Australia Pty. Ltd.

SYSTEM CERTIFICATE*

This is to certify that

PROMAT Fire Collars and Sealant

have been tested/approved in accordance with “Australian Standard 1530: Part 4
Methods for fire tests on building materials, components and structures”
protecting service penetrations through 75mm Reinforced AAC Panels

(Refer to reports: A-15-1011, A-13-816, A-15-951, A-14-879a, A-12-763, A-12-761, A-16-030, A-17-042B)

Service	Protection	Installation	Report	FRL
16mm PEX/AL/PEX	Double PROMASEAL CFC32, PROMASEAL Graf4T	Collars central in the wall	A-14-879a	-/180/120
20mm PEX/AL/PEX	Double PROMASEAL CFC32, PROMASEAL Graf4T	Collars central in the wall	A-12-763	-/120/120
20mm PEX/AL/PEX	PROMASEAL CFC32, PROMASEAL Graf4T	Collar each side of the wall	A-12-763	-/120/120
25mm PEX/AL/PEX	Double PROMASEAL CFC32	Collars central in the wall	A-15-951	-/180/60
32mm PEX/AL/PEX	Double PROMASEAL CFC32	Collars central in the wall	A-15-951	-/180/60

Service	Protection	Installation	Report	FRL
16mm PEX	Double PROMASEAL CFC32, PROMASEAL Graf4T	Collars central in the wall	A-14-879a	-/180/120
20mm PEX	Double PROMASEAL CFC32, PROMASEAL Graf4T	Collars central in the wall	A-13-816	-/180/120
20mm PEX	PROMASEAL CFC32, PROMASEAL Graf4T	Collar each side of the wall	A-12-763	-/120/90
20mm PEX	PROMASEAL AG Intumescent Sealant	PROMASEAL AG 13mm deep in 70mm hole	A-17-042B	-/120/120
25mm PEX	Double PROMASEAL CFC32, PROMASEAL Graf4T	Collars flush with one side of the wall	A-12-763	-/120/90
25mm PEX	Double PROMASEAL CFC32, PROMASEAL Graf4T	Collars central in the wall	A-13-816	-/180/90
25mm PEX	PROMASEAL CFC32, PROMASEAL Graf4T	Collar each side of the wall	A-12-763	-/120/90
32mm PEX	Double PROMASEAL CFC32, PROMASEAL Graf4T	Collars central in the wall	A-14-879a	-/180/180

* This is NOT a test certificate. For installation instructions or further information please contact Promat Australia Pty. Ltd.

Dial: 1800 PROMAT (776 628)

Email: mail@promat.com.au

Visit: www.promat.com.au

Head Office
New South Wales Office
Victoria Office
Queensland Office

1 Scotland Road, Mile End South, SA 5031 AUSTRALIA
Unit 1, 175 Briens Road, Northmead, NSW 2152 AUSTRALIA
Suite 205, 198 Harbour Esplanade, Docklands, VIC 3008 AUSTRALIA
433 Logan Road, Stones Corner, QLD 4120 AUSTRALIA

an etex company

Promat

Promat Australia Pty. Ltd.

SYSTEM CERTIFICATE*

This is to certify that

PROMAT Fire Collars and Sealant

have been tested/approved in accordance with “Australian Standard 1530: Part 4
Methods for fire tests on building materials, components and structures”
protecting service penetrations through 75mm Reinforced AAC Panels

(Refer to reports: A-15-1011, A-13-816, A-15-951, A-14-879a, A-12-763, A-12-761, A-16-030, A-17-042B)

Service	Protection	Installation	Report	FRL
40mm uPVC	PROMASEAL FC40	Retrofit both sides of wall	A-14-879a	-/180/120
40mm uPVC	PROMASEAL FCW40	Collar flush with one side of the wall	A-14-879a	-/180/90
50mm uPVC	PROMASEAL FCW50	Collar central in the wall	A-13-816	-/180/120
65mm uPVC	PROMASEAL FCW65, PROMASEAL IBS Foam, PROMASEAL A Acrylic Sealant	Collar central in the wall	A-15-1011	-/180/180
100mm uPVC	PROMASEAL FCW100	Collar central in the wall	A-13-816	-/180/120
100mm uPVC	PROMASEAL FCW100	Collar flush with one side of the wall	A-14-879a	-/180/90
100mm uPVC	PROMASEAL FC100	Retrofit both sides of wall	A-14-879a	-/180/180
100mm uPVC	PROMASTOP UniCollar	Retrofit both sides of wall	A-14-879a	-/180/120

Service	Protection	Installation	Report	FRL
56mm HDPE	PROMASEAL FCW50, PROMASEAL IBS Foam, PROMASEAL A Acrylic Sealant	Collar central in the wall	A-15-1011	-/180/180
110mm HDPE	PROMASEAL FCW100	Collar central in the wall	A-15-951	-/180/90
110mm HDPE	PROMASEAL FC100	Retrofit both sides of wall	A-15-1011	-/180/120
110mm HDPE	PROMASEAL FCW100, PROMASEAL IBS Foam, PROMASEAL A Acrylic Sealant	Collar central in the wall	A-15-1011	-/180/180

* This is NOT a test certificate. For installation instructions or further information please contact Promat Australia Pty. Ltd.

Dial: 1800 PROMAT (776 628)

Email: mail@promat.com.au

Visit: www.promat.com.au

Head Office
New South Wales Office
Victoria Office
Queensland Office

1 Scotland Road, Mile End South, SA 5031 AUSTRALIA
Unit 1, 175 Briens Road, Northmead, NSW 2152 AUSTRALIA
Suite 205, 198 Harbour Esplanade, Docklands, VIC 3008 AUSTRALIA
433 Logan Road, Stones Corner, QLD 4120 AUSTRALIA

an **etex** company

Promat

Promat Australia Pty. Ltd.

SYSTEM CERTIFICATE*

This is to certify that

PROMAT Fire Collars and Sealant

have been tested/approved in accordance with “Australian Standard 1530: Part 4
Methods for fire tests on building materials, components and structures”
protecting service penetrations through 75mm Reinforced AAC Panels

(Refer to reports: A-15-1011, A-13-816, A-15-951, A-14-879a, A-12-763, A-12-761, A-16-030, A-17-042B)

Service	Protection	Installation	Report	FRL
19mm Copper with lagged with 19mm FR Armaflex	PROMASEAL FlexiWrap	FlexiWrap through the wall and extending 75mm each side	A-13-816	-/180/120
19mm Copper wrapped with 25mm FR Armaflex	PROMASEAL A Acrylic Sealant	FR Armaflex 400mm each side of the wall	A-15-951	-/180/120
50mm Copper wrapped with 25mm FR Armaflex	PROMASEAL A Acrylic Sealant	FR Armaflex 400mm each side of the wall	A-15-951	-/180/90

Service	Protection	Installation	Report	FRL
12 x CAT 7 cables	PROMASEAL A Acrylic Sealant	40mm diameter hole, 40mm cone each side of the wall	A-13-816	-/180/180
P23 uPVC electrical conduit with fibre optic cables	Double PROMASEAL CFC32	Collars central in the wall	A-15-1011	-/180/180

Service	Protection	Installation	Report	FRL
75mm Steel pipe	PROMASEAL Pillows, Wire Mesh	Oversized hole	A-16-030	-/120/120
75mm Steel pipe	PROMASEAL A Acrylic Sealant, Wire Mesh	Sealant in 20mm annular gap and 50mm cone	A-16-030	-/120/120

Service	Protection	Installation	Report	FRL
Pair Coil with polyethylene lagging & 3-phase electrical cable	PROMASEAL AG Intumescent Sealant	Thickened with 13mm FR plasterboard both sides of the wall, PROMASEAL AG 13mm deep in 70mm diameter hole	A-17-042B	-/120/60
Pair Coil with FR lagging & 3-phase electrical cable	PROMASEAL AG Intumescent Sealant	No wall thickening, PROMASEAL AG 13mm deep in 70mm diameter hole	A-17-042B	-/120/90
Pair Coil with FR lagging & 3-phase electrical cable	PROMASEAL AG Intumescent Sealant	Thickened with 13mm FR plasterboard both sides of the wall, PROMASEAL AG 13mm deep in 70mm diameter hole	A-17-042B	-/120/120

* This is NOT a test certificate. For installation instructions or further information please contact Promat Australia Pty. Ltd.

Dial: 1800 PROMAT (776 628)

Email: mail@promat.com.au

Visit: www.promat.com.au

Head Office
New South Wales Office
Victoria Office
Queensland Office

1 Scotland Road, Mile End South, SA 5031 AUSTRALIA
Unit 1, 175 Briens Road, Northmead, NSW 2152 AUSTRALIA
Suite 205, 198 Harbour Esplanade, Docklands, VIC 3008 AUSTRALIA
433 Logan Road, Stones Corner, QLD 4120 AUSTRALIA

an etex company